
Howard County OFFICE OF TRANSPORTATION

Project Process & Timeline





FEEDBACK – WHAT WE'VE HEARD

Cars go too Fast. Particularly during commuting hours

Need a Crosswalk at Phelps Luck Drive

Generally, not enough crosswalks across Tamar Drive.



Desire for a crosswalk on all four legs

results lengthy delay on Tamar

Other Comments:



- Bus Service too Infrequent
- Need More Bus Shelters



- Lack of a Bike Lane
 - Not comfortable with on-road biking



- Convenient access to major roadsGenerally, not congested